

	A	B	C	D	E
1	<b>HW-03</b>				
2	Ex. 6-P11				
3		<b>Analyte</b>		<b>Result</b>	<b>Trigger</b>
4		methane	Wellhead	15,000 ug/L	28,000 ug/L
5			Wellhead - dup	28,000 ug/L	
6					
7	EPA Alt. Water	No			
8	Cabot Alt. Water	No-Cabot previously provided water, then Seirra Club, now from other			
9		sources, including a nearby creek			
10	Treatment	No-However, the well (located in basement) is vented to outside			
11	Proposed EPA Water	?			
12	Proposed 2nd Sampling	?			
13	<b>HW-57</b>				
14	Ex. 6-P11				
15		<b>Analyte</b>		<b>Result</b>	<b>Trigger</b>
16		iron	Wellhead	11,200 ug/L	11, 000 ug/L
17			Wellhead -filtered	U @100 ug/L	
18			Tap	U @100 ug/L	
19			Tap - filtered	U @100 ug/L	
20					
21		Arsenic	Wellhead	5.8 ug/L	4.5 ug/L
22			Wellhead - filtered	U @1 ug/L	
23			Tap	U @ 1ug/L	
24			Tap - filtered	U @ 1ug/L	
25	EPA Alt. Water	No			
26	Cabot Alt. Water	No-Per survey, Cabot previously provided water; reconditioned well in 2010			
27	Treatment	Yes-filter installed on well bladder in 2010 (not certain what type of filter?)			
28	Proposed EPA Water	?			
29	Proposed 2nd Sampling	?			